

# O<sub>2</sub>

## OXY-4/10 mini & OXY-4/10 trace

Multi-channel oxygen transmitters

Parallel monitoring of up to 10 sensors

- For use with non-invasive oxygen sensors & sensor probes
- One calibration for a multitude of sensor spots
- Software included

The OXY-4 mini, OXY-10 mini, OXY-4 trace and OXY-10 trace are precise multi-channel oxygen meters. They are used with oxygen sensors based on a 2 mm optical fiber. A PC is connected to run the easy-to-use software. OXY-4 mini and OXY-10 mini are used for sensor coatings type PSt3 (0 – 100 % oxygen). OXY-4 trace and OXY-10 trace additionally work with the trace oxygen sensor coating type PSt6 (detection limit 1 ppb, 0 – 4.2 % oxygen).



# Multi-channel oxygen transmitters

Specifications	OXY-4 mini & OXY-10 mini	OXY-4 trace & OXY-10 trace
Oxygen sensors	PSt3 only (optical SMA connector)	PSt3 and PSt6 (optical SMA connector)
Power supply	110 – 230 VAC, 50/60 Hz, max. 40 vA (cables included)	
Temperature: operating /storage	0 °C to +50 °C / -10 °C to 60 °C	
Relative humidity	up to 80 % (non condensing)	
Dimensions	300 mm x 250 mm x 135 mm	
Weight OXY-4 mini & OXY-4 trace	3,3 kg	
Weight OXY-10 mini & OXY-10 trace	3,9 kg	
Digital interface	RS 232 interface (with RJ connector to serial port, cable included)	
Software (included)	Windows 98, 2000, XP	

## Sensors & Accessories



### Sensor spots

Sensor spots are the most versatile version of non-invasive oxygen sensors. They are attached to the inner surface of any transparent vessel.



### Dipping probe

The Dipping probe is a robust invasive oxygen sensor with excellent long-term stability.



### Flow-through cell

The Flow-through oxygen minisensor is a miniaturized fiber optic chemical sensor integrated in a T-shape flow-through cell.



### Accessories

A variety of accessories like connectors to different vessels is available.

A wide variety of sensors is offered.

If your housing is missing, please contact us!