

Leica CV5030 – Configurations



For a planned connection of the CV5030 Coverslipper to the ST5020 Multistainer or ST5010 Autstainer XL, a transfer station is needed to make the two systems work with each other. Besides the CV5030 stand alone Coverslipper we also offer this instrument with already attached transfer station. In these two versions the transfer stations have been pre-adjusted with the Coverslipper for direct connection to the ST5020, ST5010 respectively. This assures time-optimized, trouble-free connections of the CV5030 to the ST5020 or ST5010. Note: Without connection of the ST5020 or ST5010 the transfer stations TS5025/TS5015 are of no function